

Studio VTR Software Versions

Model	Software Version
DNW-75	SY1 V2.17 SY2 V2.14 SV V2.18
DVW-500	SY1 V4.22 SY2 V4.12 SV1 V2.15 DT V2.02
DVW-2000	SY V6.70 SV V1.15
HDW-1800	SY1 V2.23 SY2 V2.18 SV V6.43
HDW-2000	SY V6.44 SV V6.43
HDW-F500	SY1 V2.52 SY2 V2.54 CP V2.53 PD V2.54
J-1/2/3	V2.38
J-10/30	V1.09
J-H1	V1.36
J-H3	SS V1.36 SY V1.32
MSW-2000	SY V7.30 SV V6.42 VN V4.11 (E-VTR only)
SRW-5000	V4.22
SRW-5100	V3.11
SRW-5500	V4.22
SRW-5800	V3.21

Updated: 2 December 2011

Broadcast Service Centre Ltd, 2 Andromeda House, Calleva Park, Aldermaston, Reading, Berkshire, RG7 8AN

Telephone: 0118 981 0804 Fax: 0118 981 0698 Web: <http://www.bsc-online.co.uk>

This document is supplied by BSC in good faith to help with rapid location of regularly required information. Users are responsible for determining that they fully understand the implications of any changes made to their equipment as BSC cannot be held responsible for any problems that may arise from improper use. It is highly recommended that a competent engineer makes any required changes, particularly if the covers are removed.